

Dear Valued Customer,

PCN No. 0114

PCN Type Product Replacing

Product 711-20339 Relay Holder

Date August 26, 2014


Change Notification Description

This is to announce the new 711-20339 Relay Holder which replaces the 711-2023 Relay Holder.


711-20339 Relay Holder information

A protective element has been added to the yellow wire of the Relay Holder, connected to pin 85 of the relay, in order to support Automotive Directive 2004/104/EC (E-Mark). This arrangement enforces pin 85 of the relay is connected to power and pin 86 to the unit output.



The change and the required connection are presented in the following picture and drawings.



COLOR	Pin Num
Black	30
Blue	87
Green	86
Red	87a
Yellow	85



Typical Standard Relay



You are welcome to review the [CelloFamily Hardware Installation Guide](#) for more information. Please note that the above link requires access to the [Knowledge Base Login](#) section on our website.

The change will take place immediately. For pricing and delivery information, please contact your appropriate sales manager.

Should you have any questions regarding this PCN, you are more than welcome to contact the Product Management department or your appropriate sales manager.

Kind Regards,

Natan Degani,
Cellocator Product Management Department
pm@pointer.com
Cellocator Division, Pointer Telocation LTD